

DEPARTMENT OF THE ARMY
Corps of Engineers, New Orleans District
7400 Leake Avenue
New Orleans, Louisiana 70118

CEMVN-OD-T

17 July 2018

NAVIGATION BULLETIN NO. 18-95

GULF INTRACOASTAL WATERWAY
ALGIERS LOCK

Effective immediately, mariners are advised not to tie off to nor allow their vessels to rest against the southeast guidewall at Algiers Lock, which is located on the canal end of the Lock. This guidewall is unstable and vessels tying to it or exerting force on it could cause it to fail. Operators at the Lock have been verbally advising mariners of this situation for some time.

This navigation bulletin confirms that this situation is expected to continue indefinitely and until further notice.

The Lockmaster, Thomas P. Malone, can be reached at (504) 394-5714 for up-to-date information. The points of contact with the New Orleans District are Victor Landry at (504) 862-2407 and Robert Morgan at (504) 862-2320.


STEVEN G. PATORNO
Chief, Technical Support Branch
Operations Division