

TABLE 5 continued

Hazardous Waste Code	Description
	ethyl acetate, ethyl benzene, ethyl ether, methyl isobutyl ketone, n-butyl alcohol, cyclohexanone, and methanol; all spent solvent mixtures/blends containing, before use, only the above spent non-halogenated solvents; and all spent solvent mixtures/blends containing, before use, one or more of the above non-halogenated solvents, and, a total of ten percent or more (by volume) of one or more of those solvents listed in F001, F002, F004, and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures.
F004	The following spent non-halogenated solvents: Cresols and cresylic acid, and nitrobenzene; all spent solvent mixtures/blends containing, before use, a total of ten percent or more (by volume) of one or more of the above non-halogenated solvents or those solvents listed in F001, F002, and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures.
F005	The following spent non-halogenated solvents: Toluene, methyl ethyl ketone, carbon disulfide, isobutanol, pyridine, benzene, 2-ethoxyethanol, and 2-nitropropane; all spent solvent mixtures/blends containing, before use, a total of ten percent or more (by volume) of one or more of the above non-halogenated solvents or those solvents listed in F001, F002, or F004; and still bottoms from the recovery of these spent solvents and spent solvent mixtures.
P024	Benzenamine, 4-chloro-
P024	p-Chloroaniline
P034	2-Cyclohexyl-4,6-dinitrophenol
P058	Acetic acid, fluoro-, sodium salt
P067	Aziridine, 2-methyl-
P067	1,2-Propylenimine
P068	Hydrazine, methyl-
U002	2-Propanone (I)
U002	Acetone (I)
U044	Chloroform
U044	Methane, trichloro-
U045	Methane, chloro- (I,T)
U045	Methyl chloride (I,T)
U052	Cresol (Cresylic acid)
U052	Phenol, methyl-
U080	Methane, dichloro-
U080	Methylene chloride

TABLE 5 continued

Hazardous Waste Code	Description
U086	Hydrazine, 1,2-diethyl-
U086	N-N'-Diethylhydrazine
U092	Dimethylamine (I)
U092	Methanamine, N-methyl- (I)
U101	2,4-Dimethylphenol
U101	Phenol, 2,4-dimethyl-
U103	Dimethyl sulfate
U103	Sulfuric acid, dimethyl ester
U108	1,4-Diethyleneoxide
U108	1,4-Dioxane
U109	1,2-Diphenylhydrazine
U109	Hydrazine, 1,2-diphenyl-
U112	Acetic acid ethyl ester (I)
U112	Ethyl acetate (I)
U119	Ethyl methanesulfonate
U119	Methanesulfonic acid, ethyl e
U122	Formaldehyde
U148	3,6-Pyridazinedione, 1,2-dihy
U148	Maleic hydrazide
U154	Methanol (I)
U154	Methyl alcohol (I)
U194	1-Propanamine (I,T)
U194	n-Propylamine (I,T)
U213	Tetrahydrofuran (I)
U221	Benzenediamine, ar-methyl-
U221	Toluenediamine
U228	Ethane, trichloro
U228	Trichloroethylene
U239	Benzene, dimethyl-(I,T)
U239	Xylene (I)

TABLE 6
STANDARD INDUSTRIAL CODES

Code	Description
1611	Highway and Street Construction, except Elevated Highways
2673	Plastics, Foil, and Coated Paper Bags
3273	Ready-Mixed Concrete
3569	General Industrial Machinery and Equipment, Not Elsewhere Classified

3731	Ship Building and Repairing
3799	Transportation Equipment, Not Elsewhere Classified
4121	Taxicabs
4212	Local Trucking Without Storage
5031	Lumber, Plywood, Millwork and Wood Panels
5198	Paint, Varnishes and Supplies
7216	Drycleaning Plants, except Rug Cleaning

**TABLE 7
RCRA NOTIFIERS IN CLOSE PROXIMITY TO PROJECT AREA**

Ftnote	EPA ID #	Facility Name	Location	SIC	Generator	HW Type
a	LAD092681741	Advance Polybag Inc.	2800 N Johnson	2673	3	F002,F003
a,c	LAD088923461	All Star Cleaners	1521 Elysian Fields Ave	7216	3	F002
a	LAD981154214	Alvardale Cleaners	2040 Mazant St		3	D001
a	LAD034368522	Asher Clnrs & Lndry	1309 Music St		3	F002
	LAD980510085	BASF Wyandotte Corp	5630 Douglass St		3	
	LAD985215995	Beards Auto Inc	2301 St Claude Ave		2	
	LAD981588353	Bills Texaco	5401 St Claude Ave		3	
	LAD985194083	Blanchards Body Shop	2014 Mandeville St		1	D008
a,c	LAD021028071	Boland Marine & Mfg	2500 Surekote Rd		3	
	LAD981058449	By Water Cleaners	3217 Burgundy St		3	
a,c	LAD000225771	Canal Marine Repair	2100 Surekote Rd		2	
	LAD985205780	Chevron USA Inc	1601 Franklin Ave		2	
	LAD985206069	Chevron USA Inc	1610 Elysian Fields		2	
b	LAD008155208	Citadel Cement Corp	2315 France St		1	
	LAD981515208	Clarence Jacob Auto	3233 N Calvez		2	
	LAD981586563	Cottman Transmissions	1535 Elysian Fields Ave		2	
	LAD122624042	D&G Body Shop	2231 St Claude Ave		2	
	LAD982549800	David O Shurden MD	5624 St Claude		3	
	LAD985210905	Ducros Automotive	2613 Urquhart		3	
	LAD981584493	Eldridges Auto Rpr	2045 Alvar St		2	
	LAD125487702	Everkleen Clnrs	6110 St Claude Avenue		3	
	LAD981901812	Express Auto Parts	2501 St Claude Ave		3	
	LAD985194703	Exxon Co USA #58056	1601 Elysian Fields Ave		3	
	LAD008149676	Findley Adhesives	3327 Chartres St			
c	LAD002546117	Gallagher Transfer	2401 Elysian Fields Ave			
a	LAD981905813	Herman Bros Inc	2315 France St	4121	3	F002,F004,D001,D008
	LAD985196096	High Technology Car	1641 Poland Ave		3	
	LAD981589799	James Bros & Prisco	2645 N Miro St		2	
	LAD985213941	M&M Auto Rpr	1940 Franklin Ave		3	
	LAD981591365	Mason Auto Rpr	3802 N Clatborne Ave		1	
	LAD981587256	Mini Motors	2713 St Claude Ave		2	

TABLE 7 continued

Ftnote	EPA ID #	Facility Name	Location	SIC	Generator	HW Type
	LAD981519481	Neapolen Auto Svc	3014 N Derbigny St		3	
a	LAD122613847	Ocean Technical Svc	2100 Surekote Rd		2	F002,F004,D001,D008
c	LAD981593726	Pauls Svc Cntr	1717 Franklin Ave		2	
	LAD008184921	Pelican Ice & Cold	408 Howard Ave		3	
	LAD985174119	Press Craft Printing	2206-10 Royal St		2	
	LAD981587462	Professional Auto	3113 Marais St		2	
	LAD981519812	R&G Imports & Sport	1439 Desire St		2	
	LAD008182396	Reisings Sunrise Bakery	6117 St Claude Ave		3	
	LAD985211861	Royal St Foreign Car	2430 Royal St		3	
	LA T230012718	South Central Bell	2401 Elysian Fields Ave			
	LA T230013799	South Central Bell	1740 Franklin Ave			
	LA T230014029	South Central Bell	4927 Marque Dr			
	LAD985194109	Star Collision Cent	3137 Chartres St		3	
	LAD985196914	Star Enterprise	2727 S Claiborne Ave		2	
	LAD985175579	T&T Truck Rpr	2401 Elysian Fields Ave		3	
	LAD082004219	Toms 1 Hr Clinr	3400 N Calvez		3	
	LAD034428474	Tonti Body & Fender	2120 Pori St		2	
	LAD985204098	Turner & Son	1801 Elysian Fields Ave		3	
	LAD010405983	United Medical Cent	3419 St Claude Ave		1	
b,c	LA4690310871	US Coast Guard New Orleans	4640 Urquhart St		1	
	LAD985219526	Wiz Automotive	5800 St Claude Ave		3	
c	LAD985203942	7 Up RC Bottling Co	1400 Montegut St		1	
	LAD985172527	A&A Auto Rprs & Par	4330 Laine Ave		3	
	LAD985196021	Ace Precision Fram	6017 Chef Menteur Hwy		3	
	LAD982294936	Advantage Tire Svc	3803 Downman Rd		2	
c	LAD981513369	Aero Svcs International	S Shore Harbor Drive		3	
a,c	LAD981586134	American Marine	3900 Jourdan Rd	3731	3	F003,F002,F005
	LAD985184217	American Wholesale	5501 Chef Menteur Hwy		3	
	LAD981522337	Andy's Automotive	3736 Downman Rd		2	
c	LAD096040589	Aratex Uniform Rent	3700 Desire			
a	LAD985200146	Atlantic Technical	4401 France Rd	3759	3	D001
b	LAD985206580	Atlantic Technical	5701 France Rd		3	

TABLE 7 continued

Facility Name	EPA ID #	Location	SIC	Generator	HW Type
Auto Repair Masters	LAD985202910	5880 Old Gentilly Rd		3	
Banner Chevrolet	LAD050902618	5950 Chef Menteur Hwy		2	
Bayou International	LAD042882399	5000 Old Gentilly Rd		2	
Belarus Machinery	LAD034397075	6101 Chef Menteur Hwy		3	
BFI Crescent Acres	LAD985172246	6599 Florida Ave		1	
Bill Watson Ford	LAD981608318	4700 Chef Menteur Hwy		3	
Board of Commissioners	LAD982306532	6701 S Shore Harbor		3	
Boh Bros Const Co	LAD980304331	4045 France Rd	1611	3	F002
Bunny Bread	LAD008204604	5646 Lewis Rd		3	
Cajun Camping	LAD981903446	7531 Chef Menteur Hwy		2	
Capitol Tire System	LAD981612468	3801 Downman Rd		3	
Carnesis Gulf Service	LAD981599558	8020 Downman Rd		3	
Causey Bus Svc	LAD985191063	6050 Chef Hwy		3	
Chef & I-10 Shell	LAD049047335	6700 Chef Menteur Hwy		2	
Chematron Corp	LAD041224684	6600 Gentilly Rd		2	
Chevron USA Inc	LAD985206176	4046 Chef Menteur Hwy		2	
Chevron USA Inc	LAD039432364	Lakefront Airport		2	
Chucks Auto Repair	LAD981900814	3728 Downman Rd		3	
CSX Services	LAD985220854	7801 Almanaster Ave		2	
DH Holmes Car Care	LAD010409548	4126 Chef Hwy		1	
Direct Tire Town	LAD985218130	4020 Old Gentilly Rd		3	
Don Hingles Body Shop	LAD982558942	3718 Downman Rd		3	
Dons Automotive	LAD985174101	7911 Chef Menteur Hwy		3	
Eager Aviation Corp	LAD056031701	Jimmy Wedell Hanger/Shore		3	
Eastside Auto & Tru	LAD985208024	4000 Louisa St		3	
Equitable Shipyard	LAD065459463	4325 France Rd	3731	1	F003,F005
Exxon Co USA	LAD985194711	4500 Chef Menteur Hwy		3	
Firestone Store	LAD982287039	4603 Chef Menteur Hwy		3	
Gentilly Woods Ohm	LAD981050974	4201 Chef Menteur Hwy		3	
Georges Body Shop	LAD985198159	6904 Downman Rd		3	
Georgia Pacific	LAD981520216	7500 Almanaster Ave	5031	3	D001
Greater New Orleans	LAD982563074	9380 Chef Menteur Hwy		2	

TABLE 7 continued

Footnote	EPA ID #	Facility Name	Location	SIC	Generator	HW Type
	LAD981609993	Gulf States Eng Co	252 Harbor Circle		2	
	LAD985206564	Heavy Machines Inc	7801 Almanaster		3	
	LAD985201896	Heissers Inc	7914 Chef Menteur Hwy		3	
	LAD098170368	Hertz Equip Rental	8010 Chef Menteur Hwy		3	
a	LAD980870471	Hipco Hazardous Mat	4801 Florida Ave			
a	LAD985193937	Holnam Inc	5301 France St	3273	3	D001
	LAD981585441	Housing Authority	7800 Townsend Pl		3	
	LAD985190073	Industrial Air & Hy	7400 Townsend Pl		3	
a,c	LAD008149437	International Paint	3915 Louisa St	5198	3	D001,F005
	LAD118981463	James Machine Shop	201 Harbor Circle		2	
	LAD985208479	Kansas Packing	148 Harbor Circle		2	
	LAD981608391	Kenilworth Exxon	5501 I-10 Svc Rd		3	
	LAD985208495	Kenilworth Shell	5500 I-10 at Morrison		2	
c	LAD981054489	LA Army National Guard	101 Lakefront Airport		3	
	LAD981589948	La Power House	7196 Florita Ct		2	
	LAD982286437	La Vo-Tech Sidney	3727 Louisa St		1	
	LAD981520448	Lafarge Concrete	11900 Chef Menteur Hwy		3	
	LAD034389734	Leader Buick GMC	4600 Chef Menteur Hwy		3	
	LAD981513526	Lee Dinett	8020 Downman Rd		1	
	LAD089837629	Lutheran Home of New Orl	5400 Haynes Blvd			
b	LAD980698237	M-I Drilling Fluids	5101 France Rd			
	LAD985203017	Macfrugals	3501 Jourdan Rd		3	
a,c	LAD981156961	Material Transport	3041 Inner Harbor Rd		1	See notes
	LAD985174465	McMillians Auto	8910 Old Gentilly Rd		3	
	LAD985186428	MD Specialists	7171 Downman Rd		3	
a	LAD985185412	Mechanical Equipment	3855 France Rd	3569	2	D001,D002,D008
	LAD985202571	Meineke Discount Muffler	5801 Chef Menteur		3	
	LAD094916608	Mel Motor Express	8306 Old Gentilly		1	
	LAD981902208	Million Aire of New	5500 Lakeshore		3	
	LAD108205493	Naeegele Outdoor Adv	8001 Townsend Pl		1	
c	LAD985217751	Natex Gulf South En	6801 Press Dr		3	
	LAD092105188	New Orleans Drayage	3801 Alvar St		1	

TABLE 7 continued

Facility Name	EPA ID #	Location	SIC	Generator	HW Type
b	LAD980507792	New Orleans Dresser			
	LAD982550253	New Orleans E Paint		2	
	LAD981903578	New Orleans Levee Board		3	
	LAD000757641	New Orleans Public Svc			
	LAD980867659	NL Petroleum Svc			
a	LAD990885618	NL Petroleum Svcs		2	D001,D002
	LAD122692783	Notos Body Rpr		3	
	LAD112780653	One Hour Cleaners		2	
	LAT230012502	Orleans Parish Mosq			
	LAD981511512	Orleans Parish Sch		3	
b	LAD008161275	Owens-Illinois Glas			
a	LAD060835964	Pontchartrain Dredging		2	D001,D008
	LAD985217652	Precision Tune		3	
	LAD096044144	Premier Container		3	
	LAD981591704	Professional Constr		2	
	LAD034430884	Quality Recondition		3	
b	LAD985215243	Regional Transit Auth		2	
	LAD985215383	RFB Flying Svc		3	
	LAD985210681	Ring Electric Co		3	
	LAD057119976	Roadway Express Inc		2	
	LAD981900335	Rollins Leasing Cor		3	
	LAD981521396	Ryder Truck Rental		3	
	LAD039168968	Ryder Truck Rental		1	
	LAD985197037	Salary Station		2	
	LAD040777401	Shell Service Station			
	LAD980698831	Shell Service Station			
c	LAD008178766	Simmons Ptlg & Met		3	
	LAD138097902	South Central Bell		2	
	LAD985223437	Southern Holdings		3	
a,c	LAD006947972	Southern Scrap Material		1	D001
	LAD982758781	Southern Univ at NO		2	
	LAD985203710	Sparkeys Auto Rpr		3	

TABLE 7 continued

Facility Name	EPA ID #	Location	SIC	Generator	HW Type
Speedee Oil Change	LAD985217694	4456 Chef Hwy & Louisa		3	
Star Enterprise	LAD985196930	6711 Chef Menteur Hwy		2	
Steve D Thompson	LAD981521453	4801 Almonaster		2	
Superior Auto Rpr	LAD985203835	4949 Laine Ave		3	
Taylor Energy Co	LAD985184910	5500 Lakeshore Dr William		3	
Teed's Automotive	LAD981908650	7040 Bamberry		2	
Tire Warehouse	LAD981610082	4200 Chef Hwy		3	
Turner Marine Bulk	LAD985209733	1 Elaine St		2	
United Parcel Service	LAD981521719	5700 Morrison Rd		2	
United States Gypsu	LAD082497306	5701 Lewis Rd		2	
Wagonmasters Repair	LAD981898679	4624 Downman Rd		2	
Waste Management	LAD990884462	3750 Alver St	4212	3	D001R
Wiltz Automotive	LAD981512791	8332 Chef Menteur Hwy		3	
10 Minute Oil Change	LAD981612740	6541 I-10 Service Rd		2	
DC Automotive	LAD981511702	1227 #D Center St			
Sherwin Williams	LAD070673645	1215-17 Center St			
St Bernard Parish S	LAD981588049	6601 N Rocheblave St		3	

a File viewed at LDEQ RCRA fileroom (Any notes from this source follow this table)

b No file available in the LDEQ RCRA fileroom

c Compliance history from database (Notes from Hazardous Waste Division, Compliance Section information included in Section 5.1.2.3.4.)

LAD092681741 Advance Polybag Inc. 2800 N Johnson: Site is also an on-site reuse/recycle operation. Name was changed to Atlantic Envelope Company.

LAD981154214 Alvardale Cleaners 2040 Mazant St: Dry cleaning operation at this location was terminated in 1985. Clothes are now sent to Sam Wing Cleaners for cleaning and Alvardale Cleaners functions only as a branch store. All hazardous waste was disposed of in 1985.

LAD021028071 Boland Marine & Mfg 2500 Surekote Rd: The site is inactive and control has been returned to the Board of Commissioners of the Port of New Orleans. A Site Inspection was conducted on December 6, 1983 and no items of non-compliance were noted. On May 5, 1989 a General Inspection was conducted indicating that there was no evidence of waste left on site.

LAD000225771 Canal Marine Repair 2100 Surekote Rd: A General Inspection was conducted on December 10, 1991. Large piles of sand and several dumpsters filled with empty paint cans on the property were reported. The company is now bankrupt. The spent blast sand was sampled in the presence of Dock Board employee. The analysis indicated that the sand is non-hazardous. The Port of New Orleans stated that Canal Marine subleased the site from Michael Mayer Yachts, who would be responsible for clearing the site. The paint cans were determined to be solid waste and should be disposed of at an industrial landfill.

LAD981586134 American Marine 3900 Jourdan Rd: An on-site reuse/recycle operation for company's own waste only was indicated on the notification form. Less than 90 days storage in tanks was also noted.

A RCRA Inspection was conducted on March 25, 1992. Numerous violations were noted and a penalty notice was issued as a result of this inspection. Spent sandblasting sand was used as fill on the site and a waste oil tank was uncovered and showed signs of overflowing (black streaks along the sides of the tank). Waste paint and solvents were sent to Crescent Acres Landfill for disposal (which is not authorized to receive hazardous wastes). An analysis of the waste oil indicated 9200 ppm 1,1,1-trichloroethane, 4000 ppm xylene, 450 ppm toluene, and 770 ppm ethylbenzene.

A Penalty Notice and Compliance Order was issued dated July 21, 1992. The orders charged that the facility was treating and disposing of hazardous waste without having interim status, company failed to design and maintain facility to minimize possibility of release of hazardous wastes, failed to prepare hazardous waste manifest before transporting hazardous waste to transporter and disposal facility which did not possess an active EPA ID number, failed to clean up spilled material, failed to determine if solid waste generated was a hazard, failed to make arrangements with local authorities for the types of waste handled at the facility, failed to mark waste with words 'Hazardous Waste' and accumulation date, failed to perform daily tank inspections, failed to have closure plan for a tank system without a secondary containment

system, and failed to keep containers of hazardous material closed when not in use.

LAD065459463 Equitable Shipyard 4325 France Rd: A January 12, 1983 inspection revealed the following deficiencies: facility did not implement a waste analysis plan, no personnel training records kept at the facility, less than required contingency plan, and no operating record.

A Penalty Notice was issued dated March 18, 1992. Violations included accumulating hazardous waste for greater than 90 days, and failure to have a containment system that is designed and operated in accordance with regulations.

A General Inspection was conducted on June 18, 1992. On June 9, 1992 a complaint was received from the Water Pollution Control Division at LDEQ stating that spent paint waste was dumped into the Industrial Canal by Equitable/Halter, Inc. Personnel stated that it was not their practice to dispose of waste in this manner. A tour of the facilities showed no evidence of spent paint waste or other waste materials. No Further Action was recommended. Enforcement items noted were: failure to clearly mark containers storing hazardous waste, failure to submit annual report for 1991, accumulation of waste greater than 90 days, failure to keep hazardous waste containers closed when not in use, failure to weekly inspect area where containers are stored, failure to stack containers so that each label can be read, failure to maintain inspection records, failure to have proper containment system, failure to mark containers with accumulation date, failure to retain on site a copy of all land restriction notifications for five years from the dates waste is subject to such documentation.

LAD008149437 International Paint 3915 Louisa St: A RCRA Inspection was conducted dated June 28, 1983. The site manufactures marine paints and heavy industrial coatings. The following non-compliance items were noted: improper labels, no personnel training, incorrect manifests, no daily inspection log, and no aisle space or placards in drum storage area.

At the November 29, 1983 follow-up inspection, all items of non-compliance had been corrected.

On April 22, 1991 visit, the following items were noted: many of their paints are flammable and some contain lead and chromium, no contingency plan, and no record of employee training.

LAD981156961 Material Transport 3041 Inner Harbor Rd: This site is also a transporter of hazardous wastes by highway in addition to being a generator. The types of hazardous wastes are: U122, U080, U221, U052, P058, P068, P034, P067, U101, U194, U228, U112, U239, U108, U086, U092, U103, U109, U119, U148, and U045. The land is leased from the Port of New Orleans. All wastes are disposed of off site.

A Compliance Order was issued dated December 10, 1990. The facility operates as a truck cleaning company. The respondent offered its hazardous waste to a disposal facility without an

EPA ID number, failed to determine if its hazardous waste is prohibited for land disposal, failed to determine if waste was hazardous, failed to keep a contingency plan, failed to keep record of training, and failed to acquire adequate insurance coverage for vehicles transporting hazardous waste.

A Penalty Notice was issued dated October 24, 1989.

A RCRA Inspection was conducted on April 25, 1990. The inspection indicated that all rinsate from truck cleaning process falls directly on to the bare ground. No means to collect or treat the rinsate nor prevent the rinsate from leaving the site was evident. Five samples from around the site were taken, the lab analysis showed the samples were non-hazardous, however, the presence of petroleum products and high pHs indicated illegal discharges to surface water. A water clarifying compound from a tank had also overflowed and fallen onto ground.

On April 12, 1990, between 11 am and 1 pm an employee of Material Transport was caught dumping the contents of a butyl acrylate (possible D001) truck on the ground by Ivan Fedoroff, New Orleans Sewerage and Water Board and by Tony Lapeyrouse of the Dock Board. They videotaped this process and collected samples of the liquid leaving the truck. The HazMat Unit of the New Orleans Fire Department and LDEQ Emergency Response personnel came on site later that afternoon and additional samples from the truck were collected. A Material Transport employee was cleaning the truck and stated that dumping the trucks contents on the ground was routine in the cleaning process. He said he was instructed to do so by his supervisor. LDEQ Hazardous Waste personnel told the Material Transport supervisor that the spill had to be cleaned up. The supervisor stated that the liquid was only water and non hazardous. LDEQ told him whether it was hazardous or not, it had to be cleaned up since it would be a violation of the water pollution regulations. LDEQ estimated that the spill covered a 10 x 30 foot area. As of April 25, 1990, Material Transport had not made any attempt to clean up the butyl acrylate spill, by their own admission. However, the lab results of May 4, 1990 showed that the material leaving the truck was non-hazardous. The following violations were noted: Failure to determine if a solid waste is hazardous, no contingency plan, no annual hazardous waste reports for 1987, 1988, 1989, no written record of training, no documentation showing disposal/sale of U044 and D001 wastes which were seen at previous inspection but not at this one (no longer on site).

A Follow up Inspection was conducted on June 9, 1989. The inspection revealed the following: over the past 8 months, trucks containing methyl chloride (U045), methanol (U154), corrosives (D002), organophosphate insecticides, acetone (U002), tetrahydrofurane (U213), chloroform (U044), and chloroaniline (P024) have been received and cleaned at their facility. They have not sent any wastes and/or waste-contaminated rinse water off-site.

LAD990885618 NL Petroleum Svcs 8000 Jourdan Rd: The company name was change to NL Baroid on November 23, 1987.

The site is located at corner of Haynes Blvd and Jourdan Road.

A Site Inspection of the facility was conducted on June 20, 1983. No items of non-compliance were noted. It was noted that the facility has not had any major spills. It was also noted that the facility is mostly outside storage and is very neat and clean.

LAD006947972 Southern Scrap Material 4801 Florida Ave: A RCRA Site Inspection was performed at the site, located at Florida Avenue and the Industrial Canal on May 24, 1990. The facility accepts scrap metals for recycling, etc. Wastes from parts washer (D001) are recycled by Safety Kleen.

A Notice of Violation dated November 1, 1990 was issued. The violations noted were: failure to have on file copies of hazardous waste manifests signed by the designated facility, failure to keep copy of annual hazardous waste report for 3 years, and failure to maintain contingency plan copy on-site.

C.5.1.2.3.4. OFFICE OF SOLID AND HAZARDOUS WASTE, HAZARDOUS WASTE DIVISION, COMPLIANCE SECTION. Only compliance histories from 18 of the 176 RCRA sites were obtained from this office. A Louisiana State Implementer Compliance, Monitoring, and Enforcement Report dated December 16, 1992 was obtained. LDEQ personnel indicated that the compliance histories researched for each of the 176 sites are not a complete listing of all compliance violations for the sites. Only large sites and new violations are entered into this database. One site for which the hardcopy file was pulled had an inspection conducted in 1983 which was not listed in this database printout. It is not known how many other inspections were conducted but are not included in this Initial Assessment because of the unavailability of the files from LDEQ and the gaps in data in the compliance history database. LDEQ provided no means to decipher the sites which had compliance histories associated with them but are not included in this database, although it was requested in NOD's June 10, 1993 letter described in Section C.5.1.2.3.3. The information obtained from the compliance history database follows:

LAD088923461 All Star Cleaners 1521 Elysian Fields Ave: An inspection described as an "Other Evaluation" was conducted at the site on June 5, 1989, and no items of non-compliance were noted.

LAD021028071 Boland Marine & Mfg 2500 Surekote Rd: A Compliance Evaluation Inspection was conducted on December 6, 1983 for this site and no items of non-compliance were noted. An "Other Evaluation" was conducted on May 25, 1989, and no items of non-compliance were noted. These same items were noted in the hardcopy file during the file research.

LAD000225771 Canal Marine Repair 2100 Surekote Rd: An "Other Evaluation" was conducted on December 10, 1991, with no items of non-compliance were noted. See the file research in Section 5.1.2.3.3 for items found and testing conducted.

LAD002546117 Gallagher Transfer 2401 Elysian Fields Ave: Two "Other Evaluations" were conducted at this site on May 4, 1989 and January 16, 1990. No items of non-compliance were

noted during these inspections in the database.

LAD981593726 Pauls Svc Cntr 1717 Franklin Ave: An "Other Evaluation" was conducted for this site on May 12, 1989, and no items of non-compliance were noted.

LA4690310871 US Coast Guard New Orleans 4640 Urquhart St: A Compliance Evaluation Inspection was conducted on July 11, 1989 for this site, and no items of non-compliance were noted.

LAD985203942 7 Up RC Bottling Co 1400 Montegut St: A Compliance Evaluation Inspection was conducted for this site on June 1, 1992. The following items of non-compliance were noted on the database printout: failure to prepare manifest, failure to notify of land restrictions, failure to submit an annual report, failure to have personnel contingency plan, failure to have personnel training, and failure to label containers. A Compliance Schedule Evaluation was conducted on October 1, 1992 in conjunction with an "Other Evaluation" on the same date. A Final Compliance Order with Penalty was issued on September 16, 1992.

LAD981513369 Aero Svcs International S Shore Harbor Drive: An "Other Evaluation" was conducted on April 21, 1989, with no items of non-compliance were noted in the database report.

LAD981586134 American Marine 3900 Jourdan Rd: A Compliance Evaluation Inspection was conducted for this site on March 31, 1992. The following items of non-compliance were noted as a result of that inspection: failure to clean-up hazardous waste spill, treatment of hazardous waste on site without a permit, failure to have a contingency plan, failure to manifest waste, shipment to a facility not permitted to accept hazardous waste, failure to have a training program, failure to make arrangements with local authorities, failure to characterize waste, failure to properly construct, failure to label and date containers (tank), failure to have secondary containment, failure to certify tank holding hazardous waste, failure to inspect tank daily, and failure to have a closure plan for tank without containment. The enforcement date of this is listed as July 21, 1992.

LAD096040589 Aratex Uniform Rent 3700 Desire: Two "Other Evaluations" are listed in the printout dated July 6, 1989 and September 11, 1989, no items of non-compliance are noted.

LAD065459463 Equitable Shipyard 4325 France Rd: A March 18, 1992 Compliance Evaluation Inspection was conducted with the following items of non-compliance noted: failure to mark accumulation dates on containers, failure to have container system, failure to label containers, accumulation in excess of 90 days, failure to submit annual report, failure to maintain inspection records, failure to keep containers closed, failure to inspect containers weekly, and failure to stack containers properly. An "Other Evaluation" was conducted on June 18, 1992. A Final Compliance Order with Penalty is noted dated June 19, 1992.

LAD008149437 International Paint 3915 Louisa St: A Compliance Schedule Evaluation was

conducted for the site on November 29, 1983. A Compliance Evaluation Inspection on April 22, 1991 yielded what appears to be two items of non-compliance (specifics not listed). A Final Compliance Order with Penalty was issued on August 16, 1991. See notes from file research in Section 5.1.2.3.3 for an explanation of the items of non-compliance.

LAD981054489 LA Army National Guard 101 Lakefront Airport: An October 2, 1989 Compliance Evaluation Inspection was conducted and no items of non-compliance were noted.

LAD981156961 Material Transport 3041 Inner Harbor Rd: A Compliance Evaluation Inspection was conducted on October 26, 1988 and the following items on non-compliance were noted: tank and container waste pile, no waste detention, storage without permit, containers and tank violations, personnel training and contingency plan are inadequate, and no inspection or annual reports. A June 1, 1989 Compliance Schedule Evaluation was conducted and the following items were noted: release of hazardous waste to soil, and no annual report filed. A Compliance Evaluation Inspection was conducted on January 25, 1990 and no non-compliance items are evident on the printout. An April 25, 1990 Compliance Evaluation Inspection was conducted and three items appear to be noted without a description of the items. Final Compliance Orders with Penalties were issued on the following dates: January 20, 1989; October 24, 1989 (appealed May 7, 1990); April 25, 1990; and December 10, 1990. An item labeled "Unknown" is listed with a date of May 7, 1990.

LAD108205493 Naegele Outdoor Adv 8001 Townsend Pl: A Compliance Evaluation Inspection dated February 20, 1990 was conducted and no items of non-compliance were noted.

LAD008178766 Simmons Pltg & Met 4216 Florida Ave: A May 23, 1984 Compliance Evaluation Inspection was conducted at the facility with one item of non-compliance noted but not described. A Compliance Schedule Evaluation was conducted on March 6, 1985 with one undescribed item of non-compliance noted. Another Compliance Schedule Evaluation was conducted on August 9, 1985 with no items of non-compliance noted. A Compliance Evaluation Inspection dated January 7, 1992 found the following items on non-compliance: treating hazardous waste without a permit, adding separated waste to waste water system, failing to inspect container storage area weekly, failing to keep hazardous waste containers closed, failing to label and date hazardous waste containers, failing to clean up hazardous waste spills in a timely manner, failing to have containment system, and failing to notify adm. aut. changes in HW1. On August 20, 1992 a Compliance Schedule Evaluation was conducted and no items of non-compliance were noted. Details of these violations are shown in the previous file research portion of the report in Section 5.1.2.3.3.

LAD006947972 Southern Scrap Material 4801 Florida Ave: A Compliance Evaluation Inspection was conducted on May 24, 1990 which indicates possibly two items on non-compliance (not described). A Written Informal Notice dated November 1, 1990 is also listed.

LAD981521719 United Parcel Service 5700 Morrison Rd: A Compliance Evaluation Inspection was conducted for this facility on August 9, 1989 with no items of non-compliance

noted.

C.5.1.2.3.5. OFFICE OF SOLID AND HAZARDOUS WASTE, UNDERGROUND STORAGE TANK DIVISION, ENFORCEMENT SECTION. Information on Underground Storage Tanks (USTs) is available in computer database format at LDEQ. Data was obtained from LDEQ Underground Storage Tank Division for active registered tanks within the 70117, 70126, and 70032 zip codes. USTs are a potential source of soil and ground water contamination. Most of the tanks registered contain petroleum hydrocarbon products, although other potential toxins are also noted. This office also maintains a fileroom for violations as well as monitoring required by LDEQ and quarterly reports required as a result of these violations.

Although this office has information of registered USTs in the project vicinity, there may be unregistered USTs which were illegally installed or abandoned or installed prior to the requirement to register USTs with LDEQ.

Table 8 contains the active USTs within the project vicinity. Any violations or information in the corresponding file at LDEQ follow this table.

**TABLE 8
UNDERGROUND STORAGE TANKS**

Facility	Location	Date Install	Capacity (Gal)	Type	Cont
Holy Cross School	4950 Dauphine St	Unknown	2000	Fiberglas	Unknown
Gulf Best Electric Inc	4525 N Claiborne	04/15/82	6000	Steel	Gas
Elysian Fields Sta 58056	1601 Elysian Fields	02/21/88	12000	Fiberglas	Gas
Elysian Fields Sta 58056	1601 Elysian Fields	02/21/88	10000	Fiberglas	Gas
Elysian Fields Sta 58056	1601 Elysian Fields	02/21/88	10000	Fiberglas	Gas
Elysian Fields Sta 58056	1601 Elysian Fields	02/21/88	1000	Fiberglas	Unknown
NOFD #24	1042 Poland Ave	04/30/42	2000	Steel	Diesel
NOFD #22	2041 Eganias St	04/30/59	560	Steel	Diesel
Gulf Oil Corp	1601 Franklin	04/28/76	12000	Fiberglas	Gas
Gulf Oil Corp	1601 Franklin	04/28/73	6000	Fiberglas	Gas
Gulf Oil Corp	1601 Franklin	04/28/72	8000	Fiberglas	Gas
Gulf Oil Corp	1601 Franklin	04/28/72	8000	Fiberglas	Gas
Corps of Eng Inner Harbor	4635 Urquhart St	05/23/76	800	Steel	Gas
Tenneco Oil Co #031	5201 N Claiborne	05/06/63	10000	Steel	Gas
Tenneco Oil Co #031	5201 N Claiborne	05/06/63	10000	Steel	Gas
Tenneco Oil Co #031	5201 N Claiborne	05/06/63	10000	Steel	Gas
Tenneco Oil Company #150	1535 Franklin Ave	05/06/79	10000	Steel	Gas
Tenneco Oil Company #150	1535 Franklin Ave	05/06/79	10000	Steel	Gas
Tenneco Oil Company #150	1535 Franklin Ave	05/06/79	10000	Steel	Gas
Cunningham, D H	5401 St Claude Ave	10/07/86	12000	Fiberglas	Gas
Cunningham, D H	5401 St Claude Ave	10/07/86	10000	Fiberglas	Gas

TABLE 8 (continued)

Facility	Location	Date Install	Capacity (Gal)	Type	Cont
Cunningham, D H	5401 St Claude Ave	10/07/86	10000	Fiberglas	Gas
Cunningham, D H	5401 St Claude Ave	10/07/86	8000	Fiberglas	Gas
Cunningham, D H	5401 St Claude Ave	Unknown	1000	Fiberglas	Diesel
Dennis Sheen Transfer Inc	2800 Chartres St	04/29/79	1000	Steel	Gas
U-Haul International Inc	2936 St Claude Ave	08/31/77	10000	Steel	Gas
U-Haul International Inc	2936 St Claude Ave	08/31/77	10000	Steel	Gas
U-Haul International Inc	2936 St Claude Ave	08/31/77	500	Steel	Gas
Danny's Texaco	3060 St Claude Ave	01/27/67	4000	Unknown	Gas
Danny's Texaco	3060 St Claude Ave	01/27/67	4000	Unknown	Gas
Danny's Texaco	3060 St Claude Ave	01/27/67	2000	Unknown	Gas
Danny's Texaco	3060 St Claude Ave	01/27/67	1000	Unknown	Unknown
Reising's Sunrise Bakery Inc	6117 St Claude Ave	01/27/75	6000	Steel	Gas
Reising's Sunrise Bakery Inc	6117 St Claude Ave	01/27/75	6000	Steel	Gas
Amoco Station-2567	1542 Desire St	05/05/81	8000	Steel	Gas
Amoco Station-2567	1542 Desire St	05/05/81	8000	Steel	Gas
Amoco Station-2567	1542 Desire St	05/05/81	8000	Steel	Gas
7up/RC/Bottling Co of LA Inc	1400 Montegut St	Unknown	5000	Unknown	Unknown
7up/RC/Bottling Co of LA Inc	1400 Montegut St	Unknown	6000	Unknown	Unknown
Weiser Security Services Inc	3000 St Claude Ave	05/02/81	2000	Fiberglas	Gas
Franklin Shell Service	1100 Franklin Ave	04/09/77	9528	Fiberglas	Gas
Franklin Shell Service	1100 Franklin Ave	04/09/77	9528	Fiberglas	Gas
Franklin Shell Service	1100 Franklin Ave	04/09/77	9528	Fiberglas	Gas
Yaseen Shell	5000 N Claiborne	04/09/77	9528	Fiberglas	Gas
Yaseen Shell	5000 N Claiborne	04/09/77	9528	Fiberglas	Gas
Yaseen Shell	5000 N Claiborne	04/09/77	9528	Fiberglas	Gas
Sea Gas Inc	4401 N Robertson St	05/02/82	10000	Steel	Gas
Sea Gas Inc	4401 N Robertson St	05/02/82	10000	Steel	Gas
Sea Gas Inc	4401 N Robertson St	05/02/82	10000	Steel	Gas
Unknown	420 Franklin Ave	05/02/61	1000	Steel	Gas
New Orleans Terminal Co	2952 N Dorgenois St	01/30/83	12000	Steel	Gas
New Orleans Terminal Co	2952 N Dorgenois St	01/30/83	1200	Steel	Gas
New Orleans Terminal Co	2201 St Ferdinand St	Unknown		Unknown	Diesel
New Orleans Terminal Co	St Peters&N Carrollton	Unknown		Unknown	Gas
Maloneys Mardi Gras Truck	2401 Elysian Fields	10/01/81	12000	Steel	Diesel
Maloneys Mardi Gras Truck	2401 Elysian Fields	10/01/81	12000	Steel	Diesel
Maloneys Mardi Gras Truck	2401 Elysian Fields	10/01/81	10000	Steel	Gas
Maloneys Mardi Gras Truck	2401 Elysian Fields	10/01/81	10000	Steel	Gas
Maloneys Mardi Gras Truck	2401 Elysian Fields	10/01/81	10000	Steel	Gas
Jimco Inc -NO East	11900 Chef Menteur	05/07/85	12000	Fiberglas	Diesel
New Orleans Lakefront Airport	Admin Bldg,Suite 101	05/07/66	10000	Steel	Gas
Huber Oil Co, Inc	7848 Chef Menteur	01/31/79	12000	Steel	Gas
Huber Oil Co, Inc	7848 Chef Menteur	01/31/79	12000	Steel	Diesel

TABLE 8 (continued)

Facility	Location	Date Install	Capacity (Gal)	Type	Cont
Huber Oil Co, Inc	7848 Chef Menteur	01/31/79	12000	Steel	Gas
Huber Oil Co, Inc	7848 Chef Menteur	01/31/79	12000	Steel	Gas
Downman Rd Phillips 66	4901 Downman Rd	01/31/82	8000	Steel	Gas
Downman Rd Phillips 66	4901 Downman Rd	01/31/82	8000	Steel	Gas
Downman Rd Phillips 66	4901 Downman Rd	01/31/82	8000	Steel	Gas
Harvey Press, Inc	3670 Desire Pkwy	04/28/72		Unknown	Gas
Harvey Press, Inc	3670 Desire Pkwy	04/28/72		Unknown	Empty
Gentilly Woods R/S 5-5511	4500 Chef Menteur	04/18/83	8000	Fiberglas	Gas
Gentilly Woods R/S 5-5511	4500 Chef Menteur	04/18/83	8000	Fiberglas	Gas
Gentilly Woods R/S 5-5511	4500 Chef Menteur	04/18/83	10000	Fiberglas	Gas
Gentilly Woods R/S 5-5511	4500 Chef Menteur	04/18/83	1000	Fiberglas	Unknown
Gentilly Woods R/S 5-5511	4500 Chef Menteur	04/18/83	10000	Fiberglas	Diesel
Firestone Store #4347	4601 Chef Menteur	03/28/76	500	Steel	Unknown
New Orleans, LA RCAG	Lakefront Airport	05/07/78	270	Steel	Gas
New Orleans US	Lakefront Airport	05/07/78	1500	Steel	Diesel
ECOL #9061	4500 Old Gentilly Rd	03/30/72	4000	Steel	Gas
ECOL #9061	4500 Old Gentilly Rd	03/30/72	4000	Steel	Gas
ECOL #9061	4500 Old Gentilly Rd	03/30/72	4000	Steel	Gas
ECOL #9061	4500 Old Gentilly Rd	03/30/72	8000	Steel	Gas
Dart-in Car Wash	4201 Old Gentilly Rd	05/06/76	10000	Unknown	Gas
Dart-in Car Wash	4201 Old Gentilly Rd	05/06/76	1000	Unknown	Gas
Dart-in Car Wash	4201 Old Gentilly Rd	05/06/76	10000	Unknown	Gas
Pontchartrain Park Maint Fac	4800 Hayne Blvd	11/21/87	1000	Fiberglas	Gas
New Orleans Mosquito Control	6601 Lakeshore Dr	03/05/65	3000	Steel	Gas
New Orleans Mosquito Control	6601 Lakeshore Dr	03/05/78	2000	Fiberglas	Diesel
New Orleans Mosquito Control	6601 Lakeshore Dr	03/05/78	2000	Fiberglas	Aromatic Naptha
Pontchartrain Park Golf Course	6514 Congress Dr	04/30/70	560	Steel	Gas
New Orleans Fire Dept #8	3330 Florida Ave	04/30/65	280	Steel	Diesel
New Orleans Fire Dept #6	4500 Old Gentilly	04/30/71	2000	Fiberglas	Diesel
New Orleans Fire Dept #4	6900 Downman Rd	04/30/71	280	Steel	Diesel
Central Maintenance Garage	3800 Alvar St	04/30/67	7000	Fiberglas	Gas
Central Maintenance Garage	3800 Alvar St	04/30/67	7000	Fiberglas	Diesel
Central Maintenance Garage	3800 Alvar St	04/30/67	7000	Fiberglas	Gas
Central Maintenance Garage	3800 Alvar St	04/30/67	2000	Fiberglas	Gas
Central Maintenance Garage	3800 Alvar St	04/30/67	2000	Fiberglas	Diesel
Central Maintenance Garage	3800 Alvar St	04/30/67	2000	Steel	Unknown
Chevron Facility #0108963	4046 Chef Menteur	Unknown	9728	Fiberglas	Diesel
Chevron Facility #0108963	4046 Chef Menteur	Unknown	9728	Fiberglas	Gas
Chevron Facility #0108963	4046 Chef Menteur	Unknown	9728	Fiberglas	Gas
Chevron Facility #0108963	4046 Chef Menteur	Unknown	9728	Fiberglas	Gas
American Wholesale Fence Co	5501 Chef Menteur	05/07/71	1000	Unknown	Gas

TABLE 8 (continued)

Facility	Location	Date Install	Capacity (Gal)	Type	Cont
Airtaix Aviaition, Inc	Lakefront Airport	04/15/82	12000	Fiberglas	Kerosene
Airtaix Aviaition, Inc	Lakefront Airport	04/15/82	12000	Fiberglas	Kerosene
Aero Services International	Lakefront Airport	05/05/61	10000	Steel	Avgas100ll
Aero Services International	Lakefront Airport	05/05/46	10000	Steel	Jet - A
Aero Services International	Lakefront Airport	05/05/46	10000	Steel	Jet - A
Aero Services International	Lakefront Airport	05/05/46	10000	Steel	Avgas100ll
Aero Services International	Lakefront Airport	05/05/61	2000	Steel	Gas
Aero Services International	Lakefront Airport	05/05/61	10000	Steel	Jet - A
Aero Services International	Lakefront Airport	05/05/61	10000	Steel	Jet - A
Outdoor Systems, Inc	8001 Townsend Place	04/03/74	1500	Fiberglas	Empty
Phillips 66 Company #012404	4819 Chef Menteur	04/03/64	4000	Steel	Empty
Phillips 66 Company #012404	4819 Chef Menteur	04/03/64	4000	Steel	Empty
Phillips 66 Company #012404	4819 Chef Menteur	04/03/64	4000	Steel	Empty
Phillips 66 Company #012404	4819 Chef Menteur	04/03/64	550	Steel	Empty
Phillips 66 Company #022666	4036 Chef Menteur	04/03/67	550	Steel	Empty
Phillips 66 Company #022666	4036 Chef Menteur	04/03/70	8000	Steel	Empty
Phillips 66 Company #022666	4036 Chef Menteur	04/03/70	8000	Steel	Empty
Phillips 66 Company #009838	20900 US Hwy 90	04/03/69	1000	Steel	Empty
Phillips 66 Company #009838	20900 US Hwy 90	04/03/69	6000	Steel	Empty
Phillips 66 Company #009838	20900 US Hwy 90	04/03/69	6000	Steel	Empty
Phillips 66 Company #009838	20900 US Hwy 90	04/03/69	6000	Steel	Empty
Phillips 66 Company #009838	20900 US Hwy 90	04/03/69	2000	Steel	Empty
Phillips 66 Company #04034	9028 Chef Menteur	04/03/63	4000	Steel	Empty
Phillips 66 Company #04034	9028 Chef Menteur	04/03/63	4000	Steel	Empty
Phillips 66 Company #04034	9028 Chef Menteur	04/03/63	4000	Steel	Empty
Phillips 66 Company #04034	9028 Chef Menteur	04/03/63	4000	Steel	Empty
Phillips 66 Company #04034	9028 Chef Menteur	04/03/70	560	Steel	Empty
Phillips 66 Company #010248	6318 Hayne Blvd	04/03/63	3000	Steel	Empty
Phillips 66 Company #010248	6318 Hayne Blvd	04/03/63	3000	Steel	Empty
Phillips 66 Company #010248	6318 Hayne Blvd	04/03/63	3000	Steel	Empty
Phillips 66 Company #010248	6318 Hayne Blvd	04/03/63	550	Steel	Empty
Tenneco Oil Co #127	7200 Downman Rd	05/06/69	8000	Steel	Gas
Tenneco Oil Co #127	7200 Downman Rd	05/06/69	8000	Steel	Gas
Tenneco Oil Co #127	7200 Downman Rd	05/06/69	8000	Steel	Gas
Fuelman	6050 Chef Hwy	02/01/84	10000	Steel	Gas
Fuelman	6050 Chef Hwy	02/01/84	10000	Steel	Gas
Fuelman	6050 Chef Hwy	02/01/84	10000	Steel	Diesel
Entringer Bakeries Inc	3847 Desire Parkway	02/26/68	6000	Fiberglas	Gas
Entringer Bakeries Inc	3847 Desire Parkway	02/26/68	3000	Steel	Gas
Fina Mart	6733 Chef Menteur	11/91	12000	Unknown	Gas
Fina Mart	6733 Chef Menteur	11/91	10000	Unknown	Gas
Fina Mart	6733 Chef Menteur	11/91	10000	Unknown	Gas

TABLE 8 (continued)

Facility	Location	Date Install	Capacity (Gal)	Type	Cont
Hertz Equipment Rental	8010 Chef Menteur	12/30/77	2000	Steel	Gas
Hertz Equipment Rental	8010 Chef Menteur	12/30/77	300	Steel	Unknown
Hertz Equipment Rental	8010 Chef Menteur	12/30/77	2000	Steel	Diesel
US Gypsum Co	5701 Lewis	Unknown	1000	Steel	Diesel
United Parcel Service	5700 Morrison Rd	08/91	10000	Fiberglas	Gas
United Parcel Service	5700 Morrison Rd	08/91	15000	Fiberglas	Diesel
United Parcel Service	5700 Morrison Rd	08/91	15000	Fiberglas	Diesel
Southern Scrap Material Co	4801 Florida Ave	Unknown	6000	Steel	Diesel
Southern Scrap Material Co	4801 Florida Ave	Unknown	6000	Steel	Diesel
Southern Scrap Material Co	4801 Florida Ave	Unknown	8000	Steel	Gas
Southern Scrap Material Co	4801 Florida Ave	Unknown	4000	Steel	Gas
Southern Scrap Material Co	4801 Florida Ave	Unknown	4000	Steel	Diesel
Steve Thompson	4801 Almonaster	Unknown	10000	Unknown	Diesel
Steve Thompson	4801 Almonaster	Unknown	10000	Unknown	Diesel
Steve Thompson	4801 Almonaster	Unknown	10000	Unknown	Diesel
Steve Thompson	4801 Almonaster	Unknown	8000	Unknown	Gas
Steve Thompson	4801 Almonaster	Unknown		Unknown	Unknown
Texaco	6500 Downman Rd	03/26/82	10000	Fiberglas	Diesel
Texaco	6500 Downman Rd	03/26/82	10000	Fiberglas	Gas
Texaco	6500 Downman Rd	03/26/82	10000	Fiberglas	Gas
Texaco	6500 Downman Rd	03/26/82	10000	Fiberglas	Gas
Roadway Express	3761 Louisa St	04/21/80	12000	Fiberglas	Diesel
Roadway Express	3761 Louisa St	04/21/80	12000	Fiberglas	Diesel
Banner Chevrolet	5950 Chef Menteur	Unknown		Unknown	Gas
Banner Chevrolet	5950 Chef Menteur	Unknown		Unknown	Unknown
U-Haul 74774	6210 Chef Menteur	08/31/79	10000	Fiberglas	Gas
U-Haul 74774	6210 Chef Menteur	08/31/79	10000	Fiberglas	Gas
Time Saver Stores Inc #177	6318 Hayne Blvd	04/10/85	8000	Steel	Gas
Time Saver Stores Inc #177	6318 Hayne Blvd	04/10/85	10000	Steel	Gas
Time Saver Stores Inc #177	6318 Hayne Blvd	04/10/80	8000	Fiberglas	Gas
Time Saver #33	4827 Downman Rd	04/10/77	8000	Steel	Gas
Time Saver #33	4827 Downman Rd	04/10/77	10000	Steel	Gas
Time Saver #33	4827 Downman Rd	04/10/77	8000	Steel	Gas
New Orleans Lakefront Airport	Admin Bldg,Suite 101	05/07/46	1000	Steel	Gas
New Orleans Lakefront Airport	Admin Bldg,Suite 101	05/07/46	1000	Steel	Empty
Lake Forest Shell	6500 I-10 Hwy	04/09/73	7622	Fiberglas	Gas
Lake Forest Shell	6500 I-10 Hwy	04/09/73	9520	Fiberglas	Gas
Lake Forest Shell	6500 I-10 Hwy	04/09/73	9520	Fiberglas	Gas
Lake Forest Shell	6500 I-10 Hwy	04/09/85	978	Fiberglas	Unknown
Chef & I-10 Shell	6700 Chef Menteur	05/05/82	9728	Fiberglas	Gas
Chef & I-10 Shell	6700 Chef Menteur	05/05/82	9728	Fiberglas	Gas
Chef & I-10 Shell	6700 Chef Menteur	05/05/82	9728	Fiberglas	Gas

TABLE 8 (continued)

Facility	Location	Date Install	Capacity (Gal)	Type	Cont
Chef & I-10 Shell	6700 Chef Menteur	05/05/79	500	Fiberglas	Unknown
Downman Road Shell	3901 Downman Rd	05/05/82	9728	Fiberglas	Diesel
Downman Road Shell	3901 Downman Rd	05/05/82	9728	Fiberglas	Gas
Downman Road Shell	3901 Downman Rd	05/05/82	9728	Fiberglas	Gas
Downman Road Shell	3901 Downman Rd	05/05/82	9728	Fiberglas	Gas
Schwegmanns Supermarket	5300 Gentilly Road	05/01/76	10000	Steel	Gas
Schwegmanns Supermarket	5300 Gentilly Road	05/01/76	10000	Steel	Gas
Schwegmanns Supermarket	5300 Gentilly Road	05/01/76	10000	Steel	Gas
Schwegmanns Supermarket	5300 Gentilly Road	05/01/76	10000	Steel	Diesel
Schwegmanns Supermarket	5300 Gentilly Road	05/01/76	1000	Steel	Diesel
SK Whitty & Co, Inc	3600 Desire St	05/06/75	2000	Steel	Gas
SK Whitty & Co, Inc	3600 Desire St	05/06/75	2000	Steel	Diesel
SK Whitty & Co, Inc	3600 Desire St	05/06/75	2000	Fiberglas	Diesel
Quality Reconditioning Serv	3947 Louisa St	02/26/72	1000	Steel	Gas
Hertz Equipment Rental Corp	8010 Chef Menteur	05/23/76	8000	Steel	Diesel
Hertz Equipment Rental Corp	8010 Chef Menteur	05/23/76	3000	Steel	Gas
South Shore Harbor Fuel Dock	6701 S Shore Harbor	03/31/89	10000	Fiberglas	Diesel
South Shore Harbor Fuel Dock	6701 S Shore Harbor	03/31/89	10000	Fiberglas	Gas
Orleans Levee Board	5401 Lakeshore Dr	05/08/67	2000	Steel	Diesel
Orleans Levee Board	5401 Lakeshore Dr	05/08/67	8000	Steel	Gas
Orleans Levee Board	5401 Lakeshore Dr	05/08/73	10000	Steel	Diesel
Orleans Levee Board	5401 Lakeshore Dr	05/08/73	6000	Steel	Gas
Orleans Levee Board	5401 Lakeshore Dr	05/08/80	500	Steel	Gas
Orleans Parish School Board	4300 Almonaster	05/20/71	10000	Fiberglas	Gas
Orleans Parish School Board	4300 Almonaster	05/20/82	10000	Fiberglas	Gas
Orleans Parish School Board	4300 Almonaster	05/20/71	10000	Fiberglas	Diesel
Orleans Parish School Board	4300 Almonaster	05/20/61	250	Steel	Unknown
New Orleans Lakefront Airport	Admin Bldg, Suite 101	05/08/76	2000	Fiberglas	Diesel
National Linen Service	3831 Louisa St	05/07/73	10000	Steel	Diesel
National Linen Service	3831 Louisa St	05/07/73	10000	Steel	Diesel
National Linen Service	3831 Louisa St	05/07/73	10000	Steel	Diesel
National Linen Service	3831 Louisa St	05/07/73	10000	Steel	Gas
National Linen Service	3831 Louisa St	05/07/79	10000	Steel	Gas
Fuelman	4022 Louisa St	05/01/85	12000	Steel	Diesel
Fuelman	4022 Louisa St	05/01/85	12000	Steel	Gas
Fuelman	4022 Louisa St	05/01/85	8000	Steel	Gas
Fuelman	4022 Louisa St	05/01/85	6000	Steel	Gas
Fuelman	4022 Louisa St	05/01/85	6000	Steel	Gas
Associated Hospital Svcs Inc	7639 Townsend Place	Unknown	6000	Fiberglas	Diesel

The following sites have additional information available from LDEQ Underground Storage

Tank Division in Baton Rouge, LA.

Fuelman 6050 Chef Hwy. A notification of incident report was filed dated April 24, 1993 for this site. A leak detector tripped which was found to be caused by a faulty product line. The amount of the estimated leakage of premium gasoline was noted to be less than 10 gallons.

Aero Services International, Lakefront Airport. A yellow sticky note in this file indicates "Aero Services has 2 tanks that they indicate are leaking; but are out perm but not filled with inert material". No other relevant information was in the file.

Maloneys Mardi Gras Truck Stop, 2401 Elysian Fields. A Compliance Order and Offer of Settlement is included in the file dated January 26, 1993. The file also indicated that EPA Region 6 had accepted the corrections of violations found during the inspection.

Harvey Press, Inc., 3679 Desire Pkwy. An UST Closure Notification Form dated March 22, 1990 was included in the file. No violations were noted.

Phillips 66 4901 Downman Road. The site was previously owned by Amoco Oil Co. which had a leak which required monitoring. LDEQ had since allowed Amoco to discontinue this monitoring and Phillips asked if the wells could be plugged and abandoned. LDEQ said that the wells were in good shape and could be left open.

New Orleans Terminal Co., Corner of St. Peter & N Carrollton. An UST Closure Notification Form was submitted dated April 29, 1992, indicating two tanks to be permanently closed.

New Orleans Terminal Co., 2201 St. Ferdinand. The owner of the site is listed as Norfolk Southern Railway Company. An UST Closure Notification Form was submitted to LDEQ dated April 29, 1992. A Report Notification, dated June 19, 1992 was submitted to LDEQ. The report stated that an UST was installed and operated by a lessee who vacated the site in early 1980s. A 10,000 gallon UST was removed at this location, and also 125 cubic yards of the most contaminated soil were removed. A sample taken was analyzed for TPH, TCLP, PCBs, GC/Diesel, Scan, BTEX, Oil/Grease, and VOC. The report indicates that the TCLP metals were below regulatory limits. The status of other indicated testing was not included in the file.

New Orleans Terminal Co., 2952 N Dorgenois. An UST Closure Notification Form was submitted on April 29, 1992. The form indicated that two tanks were to be permanently closed. No violations were found in the file.

7Up/RC/Bottling Co of LA, Inc., 1400 Montegut. An UST Closure Notification Form was submitted dated February 12, 1993 indicating three tanks to be removed. Soil analysis showed BTEX, and TPH(G) below detection limits in most cases.

Old Reising Bakery, 6117 St. Claude Avenue. An UST Closure Notification Form was submitted dated January 6, 1993 indicating three tanks to be removed. No violations were noted in the file.

Danny's Texaco (Star Enterprises), 3060 St. Claude Avenue. An UST Closure Notification Form was submitted to LDEQ dated October 23, 1990. The final disposition of the tank is to be sold to Southern Scarp Metal at 4801 Florida Avenue. Soil testing was conducted for benzene, toluene, ethyl benzene and xylene. An UST Inspection Report indicated that the diesel tank failed the tightness test on September 21, 1990.

Tenneco Oil Company #15016, 1535 Franklin Avenue. A leak of premium unleaded gasoline resulting from a ruptured product line was indicated in the file. Four monitoring wells and one recovery well were installed to determine contamination from this leak. The product recovery operation indicated 64 gallons of hydrocarbons and water were removed during Dec, 1985, for a total of 857 gallons recovered since the discovery.

Tenneco Station, 5201 N Claiborne Avenue. The company is quarterly reporting their required monitoring results. (Site is at the corner of N Claiborne & Lizardi streets.) Closure was granted for the site based on quarterly monitoring results in 1991.

Former Tenneco Station, 7200 Downman Road. Quarterly Reports were submitted from 1989 through 1991 for this site. A Record of Communication was included in the file dated July 27, 1989. LDEQ was on site when MW #AB-1 was installed. It was noted that at about 8 feet deep in a sand layer, a strong odor of gasoline was noted with odors dissipating at about 10 feet. The June 1989 Assessment Report showed <0.0001 ppm BTEX for soil, <0 ppm for Benzene, <0.015 ppm for Ethyl benzene, <0.01 ppm for Toluene, and <0.01 ppm for Xylene for water samples taken from MW #AB-1. The LDEQ inspector on site stated that he just could not believe the printed results. This was also noted in the inspection report dated June 30, 1989. An Official Notification from New Orleans Sewerage and Water Board dated October 20, 1986 indicates that gasoline odors in household drinking water were reported. This was the result of a PVC waterline near an UST at the station being saturated with product. A Site Assessment was conducted in June 1989 by International Technology Corp (ITT). The site is located next to the McDonalds on Downman Road.

Quality Reconditioning Serv, 3947 Louisa. As of April 2, 1992, there were no compliance problems associated with the site. A Removal Notification Form was submitted on November 29, 1990 indicated that the tanks are to be disposed of at Southern Scrap.

Fina Mart, 6733 Chef Menteur. An Inspection Report was submitted on November 12, 1992. The inspection was conducted after receiving a complaint that someone saw a new UST installed in a tank hold with no backfill in the bottom of the excavation. LDEQ confronted the owner who showed the certification card which said the excavation was backfilled with sand. No Further Action was necessary. An installation notice was submitted dated November 15, 1991. Two fiberglass coated steel tanks were noted to be

installed.

Hertz Equipment Rental, 8010 Chef Menteur Hwy. An UST Closure Notification Form was submitted to LDEQ dated June 8, 1992. Oil was discovered floating on ground water during the removal of the 500 gallon tank on July 2, 1992. It was noted that the soil is a tight clay. Samples were taken at each end of the tank. No information was available in the file on the testing results.

US Gypsum Co., 5701 Lewis Road. An UST Closure Notification Form dated April 17, 1990 was submitted to LDEQ indicating one tank to be removed. No violations were included in the file.

Texaco Station (Star Enterprises), 6500 Downman Road. A Suspected Release Report was submitted to LDEQ dated March 26, 1993. The report indicated that vapors were noted in a building. Soil borings were taken and high soil lab results were found for gasoline and diesel. The results were as follows: 590 ppm BTEX, 6800 ppm TPH and 430 ppm TPH. All lines were tightness tested and failed.

Schwegmanns Supermarket, 5300 Old Gentilly Road. Quarterly monitoring is currently being conducted for this site. The situation was discovered during an inspection on November 23, 1989. Types of product released were unleaded, unleaded plus, premium, and diesel. Four 10,000 gallon tanks all failed the tightness test. On Feb 2, 1990 PSI (Professional Services Industries Inc) installed 3 monitoring wells on site. On May 21, 1990 a Phase III Hydrocarbon Contamination Assessment was conducted for the site. Organic vapor analysis was performed on samples from soil borings, and ground water samples were tested for TPH and BTEX. Total BTEX ranged from BQL (Below Quantification Limits) to 1.03 mg/l. TPH was BQL. Free product depth ranged from 0.46' to 3.97' in the four wells. Results of Phase III assessment showed that a free product plume appears to extend to and possibly past the northern property line. The assessment indicated that off site wells are needed to determine the extent and magnitude of the plume. An Update Report was submitted to LDEQ in June 1992. Ground water at the site is estimated to flow north-north easterly at approximately 0.002 feet/foot. Free Phase product at its deepest was 3.5 inches. Approximately 2,400 gallons are estimated to be involved, also possibly under Old Gentilly Road. It is likely that free product and/or significant soil and ground water contamination has migrated north of the subject site. BTEX concentration estimated to be 5,830 square feet, TPH-G estimated at 7,770 square feet, and TPH-D estimated to be 6,550 square feet. The fourth quarter 1992 reveals elevated concentrations of BTEX and TPH in ground water samples taken from on-site wells. During this time, free product was also observed at a maximum of 1 inch depth.

C.5.1.2.4. OFFICE OF WATER RESOURCES, GROUND WATER PROTECTION DIVISION, SURVEILLANCE SECTION. The Ground Water Assessment/Remediation Site List was reviewed for locations in Orleans and St. Bernard Parishes. Seven sites in Orleans Parish, and two sites in St. Bernard Parish are listed as undergoing ground water